

ਦਫਤਰ:ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ ਬਠਿੰਡਾ  
ਤੀਜੀ ਮੰਜਿਲ, ਜ਼ਿਲ੍ਹਾ ਪ੍ਰਬੰਧਕੀ ਕੰਪਲੈਕਸ,ਬਠਿੰਡਾ

ਫੋਨਨੰ: 0164-2212878 ਫੈਕਸ ਨੰ: 0164-2213878 ਈ.ਮੇਲ:- xenbtiprov1@gmail.com

ਵੱਲ,

Principal,  
St. Xavier Convent School,  
Bajakhana-Barnala Road Dyalpura Baika.

ਨੰ: 2552

ਮਿਤੀ: 13/06/2023

ਵਿਸ਼ਾ: ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਬਾਰੇ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਆਪ ਵੱਲੋਂ ਵਿਸ਼ੇ ਅੰਕਿਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਸਾਲ 2023-24 ਲੈਣ ਲਈ ਕੇਸ ਇਸ ਦਫਤਰ ਵਿੱਚ ਪ੍ਰਾਪਤ ਹੋਇਆ ਹੈ। ਇਸ ਸਬੰਧੀ ਸਬੰਧਤ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਭਤੇਮ ਸ਼ਾਖਾ ਰਾਮਪੁਰਾਫੂਲ ਵੱਲੋਂ ਸਕੂਲ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਸਕੂਲ ਬਿਲਡਿੰਗ ਦੇਖਣ ਤੋਂ ਸਾਲ 2023-24 ਲਈ ਸੇਫ ਜਾਪਦੀ ਹੈ।

ਇਸ ਸਬੰਧੀ ਆਪ ਦੀ ਪ੍ਰਤੀ ਬੇਨਤੀ ਅਤੇ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਦੀ ਰਿਪੋਰਟ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਵਿਸ਼ੇ ਅੰਕਿਤ ਸਕੂਲ ਨੂੰ ਸਾਲ 2023-24 ਅੱਪਟੂ 31.03.2024 ਤੱਕ ਦਾ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਇਸ ਸ਼ਰਤ ਤੇ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਕਿ ਸਕੂਲ ਫਾਇਰ ਸੇਫਟੀ ਦੇ ਯੰਤਰਾਂ ਦੀ ਮਿਆਦ ਪੂਰੀ ਹੋਣ ਉਪਰੰਤ ਸਬੰਧਤ ਵਿਭਾਗ ਪਾਸੋਂ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰੀਨਿਊ ਕਰਵਾਉਣਾ ਯਕੀਨੀ ਬਣਾਏਗਾ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ  
ਬਠਿੰਡਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਭਤੇਮ ਸ਼ਾਖਾ ਰਾਮਪੁਰਾਫੂਲ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ: 1390 ਮਿਤੀ: 12.06.2023 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
ਬਠਿੰਡਾ।

# PERFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING

1. Name of the School : St. Xavier Convent School
2. Location : Baja Khana Bawal Road, Dyalpura Bhui ka
3. Plot Area : 5 Acre
4. Plinth Area : 40000 S/F
5. No. of Stories : 2 (Two)
6. Year of Construction : 2010
7. Whether the building has been constructed under the supervision of the qualified Engineer, if so.
  - a) Name of the Engineer with qualification : Enr. Mienish Bansal (M. Arch)
  - b) Address : 98551-22226 Eden Architect Biki wala Road  
98553-22226 opp DAV college Bathinda
  - c) Set of structural drawing used in construction : \_\_\_\_\_
8. Whether the building has been constructed for the purpose of: -
  - a) School : (Yes / No)  Yes
  - b) Residential purpose (or) : (Yes / No)  NO
  - c) Converted for school : (Yes / No)
9. Material used for Roofs: -
  - a) R.C.C. Slab : (Yes / No)  Yes
  - b) R.S. joints & Battens : (Yes / No)
  - c) Wooden Joints & Battens : (Yes / No)
10. Material used for Walls: -
  - a) Mud Mortar : (Yes / No)
  - b) Cement Mortar : (Yes / No)  Yes
  - c) Plaster :
    - Lime Mortar : (Yes / No)
    - Cement Mortar : (Yes / No)
11. Flooring: -
  - a) Conglomerate : (Yes / No)  Yes
  - b) Terrazo : (Yes / No)  Yes
  - c) Brick Paving : (Yes / No)

12. A detailed drawing indicating dimensions of the rooms & location of doors and windows is attached.

13. General

- i) In case of double story building 1.5 meter width upstairs are Constructed or not : (Yes / No)  Yes
- ii) Whether all class room are provided two door system. : (Yes / No)  Yes
- iii) Whether fire safety measures have been adopted and are in working condition. : (Yes / No)  Yes

Dated: 08-05-2023

Signature of Principal with school stamp




(For the use of the PWD B&R department).

- a) I Nishu Bansal S.D.E. alongwith Kuldeep Singh J.E. have visited this school on 7/6/23 and have inspected it from all angles of safety and found it fit for normal use as school building.
- b) In case any addition, alteration, extension or modification of this building is to be carried out, it should be carried out under the supervision of technical qualified Engineer, and after its completion, this certificates may again be obtained from the undersigned.
- c) In case the building is affected by flood or if there is settlement to walls foundations, edging or roof, immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) The building can be safely occupied for normal use upto 31/3/2024
- e) Inspection fee has been deposited by the school vide G.R. No. \_\_\_\_\_ dt. \_\_\_\_\_ amounting to Rs. 10,000/-.

Countersigned

Executive Engineer,

  
Sub Divisional Engineer,  
Sub Divisional Engineer  
Constn. Sub Divn. P.W.D.(B&R) Br.,  
Rampura Phul